SERVICE BULLETIN

Date: May 23, 2017 **Update Number:** S2017-07

Subject: Replacement Parts for Automatic Garage Door Lock Capable Garage Door Openers

Products Affected: LiftMaster® Models 8550W, 8587W, and 8360W

LiftMaster® is proud to introduce the new Auto Lock Capable garage door opener Models 8550W, 8587W, and 8360W.

The new models are compatible with the Automatic Garage Door Lock Model 841LM, which includes 33 feet of installation wire.

Identifying features of the new 8550W, 8587W, and 8360W models:

Product packaging displays the "Auto Lock Capable" header with the Shield icon.





- Product's opener chassis cover displays the Shield icon.
- Product manual and product label are marked with the letter "L" (e.g., 8550WL).
- Product's side or back have two (2) lock terminals next to program arrows.

New service kits are available for the Auto Lock Capable garage door opener models, and are not interchangeable with the non-lock models. We will continue to support and supply logic boards for all model versions.

UNIQUE SERVICE KITS PART LIST:

NON LOCK CAPABLE UNITS	
Part #	Description
050DCTWF	DC Wi-Fi® Receiver Logic Board
050ACTWF	AC Wi-Fi® Receiver Logic Board
041D8198	End Panel (Logic Board)

LOCK CAPABLE UNITS		
Part #	Description	
050DCTWFLK	DC Wi-Fi® Lock Receiver Logic Board	
050ACTWFLK	AC Wi-Fi® Lock Receiver Logic Board	
041D0216-2	End Panel (Logic Board)	

Service kits will be available to order after 08/02/2017.

Thank you for your continued support of LiftMaster. If you have any questions regarding the information above, please contact your LiftMaster Sales Representative or visit us at Support.LiftMaster.com. For a complete listing of our Product and Service Bulletins, please visit Dealer.LiftMaster.com.

